

CORRES. CONTROL
INCOMING LTR NO.

00253 RF04

DUE DATE

ACTION

DIST.	LTR	ENC
BERARDINI, J.H.	X	
BOGNAR, E.S.	X	
BROOKS, L.	X	
BUTLER, L.	X	
CARPENTER, M.	X	
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K. R.		
DIETER, T. J.		
FERRERA, D. W.	X	
GIACOMINI, J. J.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NESTA, S.	X	
NORTH, K.	X	
RODGERS, A. D.		
SHELTON, D. C.	X	
SPEARS, M. S.	X	
PIZZUTO, V.M.		
TOBIN, M.	X	
TUOR, N. R.	X	
WIEMELT, K.	X	
WILLIAMS, J. L.		
ZAHM, C.	X	

COR. CONTROL	X
ADMIN. RECORD	X
PATS/130	

Reviewed for Addressee
Corres. Control RFP6/14/04
Date By

Ref. Ltr. #

DOE ORDER #

5400.1

RECEIVED

2004 JUN 14 P 2:53

STATE OF COLORADO

Bill Owens, Governor
Douglas H. Benevento, Executive DirectorCORRESPONDENCE
CONTROL

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S.
Denver, Colorado 80246-1530
Phone (303) 692-2000
TDD Line (303) 691-7700
Located in Glendale, ColoradoLaboratory and Radiation Services Division
8100 Lowry Blvd.
Denver, Colorado 80230-6928
(303) 692-3090Colorado Department
of Public Health
and Environment

June 9, 2004

Mr. Joe Legare

Acting Assistant Manager for Environment and Stewardship

U.S. Department of Energy, Rocky Flats Project Office

10808 Highway 93, Unit A

Golden, CO 80403-8200

RE: Closeout Report for Building 566/566A - Approval

Dear Mr. Legare:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed your letter and the Closeout Report for Building 566/566A, dated April 22, 2004, and received on April 26, 2004. We have also received your letter dated June 7, 2004 and additional information in response to our email comments. Building 566/566A was previously determined to be a Type 2 Facility. As such, and based on the information provided, we are hereby approving this Closeout Report for Building 566/566A, with the following comments:

1. The remaining B566 infrastructure, the pit floor, is indicated to be 10 feet below final grade. Although this may have been correct for the projected final grade at the time of the building demolition, the current land configuration plans, as of May 12, 2004, indicate that this pit floor may now be at or within 3 feet of the final grade. As such, this pit floor may need to be removed during the final grading of this area.
2. In addition, other remaining in ground infrastructure associated with B566, including the process waste lines, sanitary sewer lines, plant water lines, etc, may now be within three feet of the current projected final grade, and may need to be removed.


If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruehek at (303) 692-3328.

Sincerely,

Steven H. Gunderson
RFCA Project Coordinator

cc: Gary Morgan, DOE
Mark Aguilar, EPA
Steve Nesta, KH
Administrative Records Building T130G

Karen Wiemelt, KH
Dave Shelton, KH
David Abelson, RFCLO



ADMIN RECORD

1A-A-002166